Kentucky **Energy and Environment Cabinet** Department for Natural Resources

From:

Carl E. Campbell, Commissioner

Date:

C.E.C. April 1, 2011

Subject: KPDES Permits for Coal Mining Activities:

Permitting, Reporting and On-site Record-

Keeping Requirements

Reclamation Arivison Memorandun,

PAM # 149

Effective Date: As noted by section.

Introduction

The Kentucky Department for Natural Resources (D. Vis providing Vis document as a service to the regulated community and as a courtesy to the Department for Environmental Protection (DEP) Division of Water (DOW).

This memorandum serves to clarify Kentuck Polluta charge Elimination System (KPDES) permitting and Discharge Monitoring Report (Legion equire) ents for coal mining activities. It also includes requirements to provide information about the laboratory that provides KPDES DMR data and SMCRA surface water and group r monitor; data for each permit.

KPDES Permits and Coverage F. viren ective Date: April 1, 2011)

- 1. Every new (NW) SMC' A permit is required to have KPDES permit coverage prior to initiation of any disturt ance of the permitarea. This requirement includes underground-only permits and road-o' permi.s.
- 2. A KPDES application is a ruired to be submitted to DOW for every subsequent SMCRA permitting action in adds me than one (1) surface acre. The only exception to this rule is acreage dded if an existing SMCRA permit exclusively in response to a noncompliance is and by the DNR Division of Mine Reclamation and Enforcement (DMRE) or DEP Division of Librarcement (DENF).
- 3. KPDES covered begins with issuance of the KPDES permit and must be maintained for the entire SMCR permit area through Phase III Bond Release.
- 4. These equirements apply to both KPDES Individual permits and Coal General permit coverage

gy and invironment Cabinet does not discriminate on the basis of race, color, national origin, sex, age, religion,
or ulsability and provides, on request, reasonable accommodations including auxiliary aids and services necessary to
afford an individual with a disability an equal opportunity to participate in all services, programs, and activities. To
request "ublication in an alternative format, contact: Office of the Commissioner, Department for Natural Resources,
2 Hudson Follow, Frankfort, Kentucky 40601-4321.

(502) 564-6940 ☐ FAX (502) 564-5698 ☐ e-mail: Carl.Campbell@ky.gov TTY (502) 564-0183 (text telephone for the deaf, hard of hearing, or speech-impaired) RAM # 149 KPDES Permits for Coal Mining Activities April 1, 2011 Page 2 of 3

KPDES Reporting Requirements (Effective Date: Second Quarter 2011 DMR Submittal)

- 1. The KPDES permittee must begin submitting DMRs according to the frequency specified in the KPDES permit upon issuance of the KPDES permit or coverage regardless of the status of the permit area or permitted outfalls. This applies to both undisturbed permits and unconstructed outfalls.
- 2. The permittee must list on the DMR Cover Sheet for every DMR submittal all permitted KPDES outfalls for the permit and the KPDES discharge status for each outfall. Outfalls that have not been constructed should be shown with a status of **NC** (not constructed) and outfalls that have been removed should be shown with a status of **REM** (removed).
- 3. A discharge report is required for <u>every</u> approved outfall whether constructed, discharging or removed. If no discharge was recorded for a given outfall, a DMR must be submitted with "Y" in the No Discharge Report box and an explanation (including not constructed or removed, if appropriate) in the comments box. An explanation is likewise required if the reported sampling frequency is less than that required by the KPDES permit conditions for the site.
- 4. If alternate precipitation limits are requested, information must be submitted as part of the DMR to support the request. This information must include precipitation data from a precipitation gauge maintained on the permit site or within a five (5) mile radius that can be corroborated with NOAA or other official precipitation data, and may be supported by weir flow measurements, dated photographs, or equivalent proof of record.
- 5. Responses must be provided for <u>all</u> fields in the header of the DMR form for each outfall.
- 6. An explanation is required in the comments box of the DMR form for every self-reported exceedance.

Water Laboratory Information (Effective Date: April 1, 2011)

- 1. The permittee must include on each DMR cover sheet the name of the laboratory that provided the water data reported on the DMR.
- 2. The permittee must provide the Division of Mine Reclamation and Enforcement with the name and address of the water laboratory that will provide DMR data when the initial KPDES permit is issued for a site, and whenever a different water laboratory is engaged to provide the reported DMR data. The attached Water Laboratory Selection Notification Form should be sent by email or hardcopy to Clay Baxter, clay.baxter@ky.gov, Division of Mine Reclamation and Enforcement, #2 Hudson Hollow, Frankfort, KY 40601.

RAM # 149 KPDES Permits for Coal Mining Activities April 1, 2011 Page 3 of 3

On-Site Records Required (Effective Date: April 1, 2011)

The following records and documents are required by the KPDES permit to be kept at the permit site (mine site) and to be readily available to cabinet inspectors upon request.

- 1. A copy of the current KPDES permit or coverage.
- 2. A copy of the KPDES best management practices (BMP) plan for the site (reviewed and updated at the frequency specified by the KPDES permit or coverage, and as necessary).
- 3. BMP training and review records.
- 4. A copy of any required SPCC or GPP for the site.
- 5. A log of bypasses and overflows resulting in discharges from the site. These events should also be reported on the DMR for the quarter in which they occur.
- 6. An on-site precipitation log if alternate effluent limitations are to be requested and there is no other source of precipitation data within a five (5) mile radius that can be corroborated with NOAA or other official precipitation data.

If you have questions about the issues discussed in this RAM, please contact either the Director, Division of Mine Reclamation and Enforcement, #2 Hudson Hollow, Frankfort, Kentucky 40601, (502) 564-2340, or the Director, DEP Division of Water, 200 Fair Oaks Lane, Frankfort, KY 40601, (502) 564-3410. Additional information about KPDES permits can be found at: http://water.ky.gov/permitting/Pages/Mining.aspx

Attachment: Water Laboratory Selection Notification Form